



BOSCH

February 02, 2021

Robin Lawson, BT-CO/ENG3.1
Sr. Mechanical Engineer
Telex Aviation Products
Tel +1 952 736-3987
Robin.Lawson@us.bosch.com

Robert Bosch LLC
12000 Portland Ave. S.
Burnsville MN 55337 USA
Tel 877-863-4166
Fax 952-884-0043
www.bosch.us

RE: Storage and Care of Telex Aviation Headsets

Ladies and Gentlemen,

It is recommended to store Telex Aviation headsets in a fully-zipped carrying case after each use in order to improve the environmental protection. To further protect against moisture it is recommended that appropriate desiccants be used in the headset case.

Regardless of whether or not a carrying case is used, headsets should be stored in a dry and temperate environment. Headsets should also be kept out of direct sunlight whenever possible to avoid unnecessary degradation.

The following general care guidelines are recommended in order to maintain the airworthiness of Telex aviation headsets.

- To ensure proper function, keep the microphone away from excessive moisture and use the appropriate windscreen.
- When removing the headset from a cockpit connection pull on the plug instead of yanking on the cable.
- Use a damp cloth to gently wipe down your headset periodically, after many hours of use. Allow it to dry completely before wearing or storing.
- Please refer to the relevant section of the maintenance manual for proper cleaning methods and never spray liquid directly onto the headset or submerge any part of the headset in water or liquid. Caution: In case the headset is immersed in water or other liquid, do not use the headset and contact Technical Support for assistance.



- When storing the headset in a carrying case wrap the cable carefully and avoid sharp bends, especially where it connects to the earcup.
- Inspect ear cushions, headband pad, and microphone windscreen frequently for wear-and-tear. It is recommended they be replaced at 6-month intervals. For optimal hygiene replace them more often.
- Inspect and clean the plugs regularly to make sure they are free from dirt or defects.
- If any defects such as cracks in the ear cup housing or cable are observed, the headset should be repaired or replaced.

Yours sincerely,

A handwritten signature in cursive script that reads "Robin Lawson".

Robin Lawson
Sr. Mechanical Engineer
Telex Aviation Products