



Concorde Battery Corporation
 2009 San Bernardino Road
 West Covina, CA 91790
 Phone (800) 757-0303 or (626) 813-1234
 Fax (800) 237-4209 or (626) 813-1235
 Email: customer-service@concordebattery.com
<http://www.concordebattery.com>

An ISO 9001:2008 + AS9100C Certified Company

Eligibility List

Revision: EL-70 (Revised: 10-10-12)

(Contact Concorde factory or consult website for latest revision number)

FAA Approval Information

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Aerofab Inc.	(See Revo Inc.)			
Agusta	A109C, A109E, A119, AW119 MKII (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# SR09360RC	RG-407	FAA-PMA Supplement No. 57, dd 06/16/03 and FAA TSO-C173 (Amendment to STC to add AW119 MK II on 01/15/10)
Agusta	A109A, A109C, A109E (To replace nickel-cadmium battery – Contact Rotorcraft Support for replacement details prior to battery purchase)	STC# SR01456LA	RG-407	FAA-PMA Supplement No. 62, dd 10/30/03 and FAA TSO-C173
Agusta	AW139 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# SR03072NY	RG-380E/44L or RG-380E/60L	FAA TSO-C173
Alon	(See Univair)			
American Champion	7ECA, 7GCAA, 7KCAB	TC# A-759	RG-25	FAA-PMA Supplement No. 31, dd 06/03/97
American Champion	8GCBC, 8KCAB	TC# A-21CE	RG-25	FAA-PMA Supplement No. 31, dd 06/03/97
Aviat Inc. / Sky International	Aviat Model A-1A, A-1B Aviat Pitts Model S-2C	TC# A22NM & A8SO	RG-25	FAA-PMA Supplement No. 42, dd 08/06/01
Aviat Inc. / Sky International	Aviat Model A-1 Aviat Pitts Models S-1S, S-1T, S-2, S-2A, S-2S, S-2B	TC# A22NM & A8SO	RG-25	FAA-PMA Supplement No. 18, dd 08/02/95
Avions de Transport Regional (ATR)	ATR42 Series; ATR72 Series (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST03930AT (Kit)	RG-380E/44 (Main) RG-42 (Emergency) 7945 (Dummy temp. sensor); 6716 Placard	FAA-PMA Supplement No. 97, dd 09/28/11 & P/N RG-380E/44 and RG-42 are FAA TSO-C173 authorized
B-N Group Ltd.	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, BN-2T-4R	FAA Design Approval	RG-390E	FAA-PMA Supplement No. 34, dd 11/18/97 and FAA TSO-C173
Bell	206A & 206B (To replace nickel-cadmium battery – Contact Adv. Pwr. For replacement details prior to battery purchase)	STC# SR00318SE	RG-206	FAA-PMA Supplement No. 26, dd 06/21/96 and FAA TSO-C173
Bell	206A & 206B (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	STC & STA# SR09054RC	RG-206	FAA-PMA Supplement No. 23, dd 04/04/96 and FAA TSO-C173
Bell	204B, 205B, 205A-1, 212, 412 (To replace nickel-cadmium battery – Contact Adv. Pwr. for replacement details prior to battery purchase)	STC# SR00173SE	RG-380E/44	FAA-PMA Supplement No. 20, dd 11/13/95 and FAA TSO-C173
Bell	212 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Bell	214ST (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase) (Battery avail. through STC holder)	STC# SR09225RC	RG-214	FAA-PMA Supplement No. 45, dd 10/22/02
Bell	222U (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	STC# SR09142RC	RG-380E/44	FAA-PMA Supplement No. 30, dd 05/18/97 and FAA TSO-C173
Bell	212, 412, 412EP (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	STC & STA# SR09053RC	RG-380E/44	FAA-PMA Supplement No. 23, dd 04/04/96 and FAA TSO-C173
Bell	206L-1, 206L-3, 206L-4 (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	STC & STA# SR09069RC	RG-222	FAA-PMA Supplement No. 25, dd 06/07/96 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Bell	206L, 206L-1, 206L-3, 206L-4 (To replace nickel-cadmium battery – Contact Adv. Pwr. For replacement details prior to battery purchase)	STC# SR00462SE	RG-222	FAA-PMA Supplement No. 48, dd 12/02/02 and FAA TSO-C173
Bell	407 (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase) (Battery avail. through STC holder)	STC# SR09359RC	RG-407A1	FAA-PMA Supplement No. 58, dd 06/19/03
Bell	407, 430 (To replace nickel-cadmium battery – Contact Rotorcraft for replacement details prior to battery purchase)	STC# SR01456LA	RG-407	FAA-PMA Supplement No. 62, dd 10/30/03 and FAA TSO-C173 Supplement amended 10/04/2012 to inc. Bell 430
Boeing	737-600, -700, -800, -900 Series (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST03932AT (Kit)	RG-380E/60B 9507 (Dummy Temperature Plug)	FAA-PMA Supplement No. 96, dd 09/28/11 and P/N RG-380E/60B is FAA TSO-C173 authorized
Bombardier Inc.	BD-100-1A10 (Challenger 300) (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST01488WI (Kit)	RG-441 5-0123 (TS-C3 Temperature Sensor)	FAA-PMA Supplement No. 85, dd 01/07/09 & P/N RG-441 is FAA TSO-C173 authorized.
Bombardier Inc.	CL-600-2B16, -2B19, -2C10, -2D24 (To replace nickel-cadmium batteries – Contact Concorde for replacement details prior to battery purchase)	STC# ST01646WI (Kit)	RG-380E/44L (APU); RG-223 (Main); 5-0166 (TS-C11A, Temp Sensor); 5-0283 (TS-C11B, Temp Sensor)	FAA-PMA Supplement No. 99, dd 01/13/12 and P/N RG-380E/44L & RG-223 are FAA TSO-C173 authorized.
Bombardier Inc.	DHC-8-100, -200, -300 (To replace nickel-cadmium batteries – Contact Concorde for replacement details prior to battery purchase)	STC# ST01643WI (Kit)	RG-380E/44 or RG-380E/60L & 5-0290 (Installation kit)	FAA-PMA Supplement No. 95, dd 09/09/11 and RG-380E/44 & RG-380E/60L are FAA TSO-C173 authorized
British Aerospace	Jetstream 3101 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# SA2994SO	RG-390E	FAA-PMA Supplement No. 16, dd 05/18/92 and FAA TSO-C173
British Aerospace	Jetstream 3201 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# SA2995SO	RG-390E	FAA-PMA Supplement No. 16, dd 05/18/92 and FAA TSO-C173
British Aerospace	Jetstream 3201 (S/N: 790 – 9999) (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST00342LA	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 32, dd 06/11/97 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Cessna	<p style="text-align: center;">SINGLE ENGINE MODELS</p> <p>120, 140, 140A, 150, 150A, 150B, 150C, 150D, 150E, 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, 152, A152, 170, 170A, 170B, 172, 172A, 172B, 172C, 172D, 172E, 172F (USAF T-41A), 172G, 172H (USAF T-41A), 172I, 172K, 172L, 172M, 172N, 172P, 172Q, 172R, 172S, 175, 175A, 175B, 175C, P172D, R172E (USAF T-41B)(USAF T41C&D), R172F(USAF T-41D), R172G ((USAF T-41C & T-41D), R172H (USAF T-41D), R172J, R172K, 172RG, 177, 177A, 177B, 177RG, 180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K, 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R/T182, R182, TR182, 182S, 182T, T182T, 185, 185A, 185B, 185C, 185D, 185E, A185E, A185F, 188, 188A, A188, A188A, 188B, A188B, T188C, 190, 195, 195A, 195B, 206, 206H, U206, P206, U206A, P206A, P206B, TU206A, TU206B, TP206A, TP206B, U206B, P206C/TP206C, P206D/TP206D, P206E/TP206E, U206C/TU206C, U206D/TU206D, U206E/TU206E, U206F/TU206F, U206G/TU206G, T206H, 207/T207, 207A/T207A, 305B, 305E, 210, 210A, 210B, 210C, 210D, 210E, 210F, T210F, 210G, T210G, T210H, 210H, T210J, 210J, 210K/T210K, 210L/T210L, 210M/T210M, 210N, P210N, T210N, 210R, P210R, T210R, 210-5 (205), 210-5A (205A), 305B, 305E (Military TO-1D, O-1D, O-1F), 337, 337A (USAF O2B), 337B, 337C, 337D, 337E, 337F, 337G, 337H/T337H, T337B, T337C, T337D, T337E, T337F, T337G, M337B (USAF O2A), P337H, T337H-SP</p> <p style="text-align: center;">TWIN ENGINE MODELS</p> <p>T303, 310, 310A (USAF U-3A), 310B, 310C, 310D, 310E (USAF U-3B), 310F, 310G, 310H, E310H, E310I, E310J, 310J, 310J-1, E310K, 310L, 310N, 310P, T310P, 310Q, T310Q, 310R, T310R, 320, 320-1, 320A, 320B, 320C, 320D, 320E, 320F, 335, 340, 340A, 401, 401A, 401B, 402, 402A, 402B, 402C, 404, 411, 411A, 414, 414A, 421, 421A, 421B, 421C</p>	STC# SA01118WI (See Note 3)	<p>CB-25 CB-25XC RG-25 RG-25XC Replaces original battery p/n 0511319-1</p> <p>CB-35A CB-35AXC RG-35A RG-35AXC Replaces original battery p/n 0712605-1 or 0712604-1 or 0311053</p> <p>CB-24-11 RG24-12 RG24-16 (P/N RG24-11 and RG24-15 are approved for installation, but are not recommended due to some fitment issues.) Replaces original battery p/n C614001-0106</p> <p>CB-24-11M RG-24-11M RG-24-15M Replaces original battery p/n C614002-0102</p> <p>RG24-10 (P/N RG24-9 is approved for installation, but not recommended due to some fitment issues) Replaces original battery p/n C614001-0105</p> <p>RG24-20 Replaces original battery p/n 5018200-201 & REBAT p/n R2425</p>	FAA-PMA Supplement No. 83, dd 9/20/07 Amended 10/21/09

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Cessna	120, 140, 140A, 170, 170A, 170B, 172 thru 172Q, 172R, 172S, 210, 210A thru 210R, T210F thru T210R, P210N, P210R, 210-5, 210-5A, 175, 175A, 175B, 175C, 172RG, P172D, R172E, R172F thru R172K, 177, 177A, 177B, 177RG, 180, 180A thru 180K, 185, 185A thru 185E, A185E, A185F, 188, 188A, 188B, A188, A188A, A188B, T188C, 206, U206, P206, U206A, P206A, P206B, TU206A, TU206B, TP206A, TP206B, U206B, P206C/TP206C thru P206E/TP206E, U206C/TU206C thru U206G/TU206G, 206H, 207, 207A, T207, T207A, 305B, 305E, 337, 337A thru 337H T337B thru T337H, M337B, P337H, T337H-SP, 150, 150A thru 150M, A150K thru A150M, 152, A152	STC# SA00897WI (See Note 3)	RG-25 or RG25XC Replaces original battery p/n 0511319-1 RG-35A or RG35AXC Replaces original battery p/n 0712605-1 RG24-11 RG24-15 Replaces original battery p/n C614002-0102 RG24-11M RG24-15M Replaces original battery p/n C614001-0106	FAA-PMA Supplement No. 43, dd 09/04/01
Cessna	210 (S/N: 21059503 & on), T210	STC# SA2558CK	RG24-11M	FAA-PMA Supplement No. 14, dd 02/07/91
Cessna	182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, R182/TR182, 182R/T182 (182 Series through S/N: 18265965 Except: 18263479)	STC# SA00753WI	CB-35A RG-35A RG-35AXC	FAA-PMA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02
Cessna	182 Series (S/N: 18263479, 18265966 and up), R182 and TR182 Series (S/N: R18200001 and up)	STC# SA00753WI	RG24-15	FAA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02
Cessna	425 (Conquest I) (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	STC# SA2435CE	RG-380E/44	FAA-PMA Supplement No. 14, dd 02/07/91 and FAA TSO-C173
Cessna	425 (Conquest I) (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	STC# SA2436CE	CB24-380E	FAA-PMA Supplement No. 14, dd 02/07/91
Cessna	441 (Conquest II) (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	STC# SA2496CE	RG-380E/44	FAA-PMA Supplement No. 14, dd 02/07/91 and FAA TSO-C173
Cessna	441 (Conquest II) (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	STC# SA2247CE	CB24-380E	FAA-PMA Supplement No. 14, dd 02/07/91
Cessna	550 (Citation II) Series (To replace stand-by nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST01639LA	RG-131	FAA TSO-C173
Cessna	(Caravan) 208, 208B (Replaces p/n RG-380E/44 or RG-380E/40B w/ two (2) RG-390E in conjunction with engine conversion)	STC# SA10841SC	RG-390E	FAA-PMA Supplement No. 89, dd 10/27/09 and FAA TSO-C173
Cessna	(Caravan) 208, (Citation II) 500, 501, 550, 551 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Cessna	(Caravan) 208, 425, 441, (Citation II) 500, 501, 550, 551 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Cirrus	SR20, SR22	STC# SA01304WI	CB24-11M, RG24-11M, RG24-15M	FAA-PMA Supplement No. 76, dd 02/18/05
Dassault	Falcon 10 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST00774LA (Kit)	RG-390E, 9899 (temp sensing tray)	FAA-PMA Supplement No. 39, dd 04/23/99 P/N RG-390E is FAA TSO-C173 authorized

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Dassault	Falcon 20 Series, C, D, E, F (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Dassault	Falcon 20 Series, C, D, E, F (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Dassault	Falcon 50, 50EX, 900, 900EX, 900DX, 2000, 2000EX (Emergency battery replacement only to replace nickel-cadmium or lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST01571WI	RG-128 Series	FAA-PMA Supplement No. 90, dd 02/12/10 and FAA TSO-C173
Dassault	MF 50 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase) (Battery Mod. avail. through Dassault)	FAA Design Approval	RG-390E/LS	FAA-PMA Supplement No. 51, dd 02/21/03 and FAA TSO-C173
Dassault	Falcon MF900, F900EX To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase) (Battery Mod. avail. through Dassault)	FAA Design Approval	RG-390E/LS	FAA-PMA Supplement No. 51, dd 02/21/03 and FAA TSO-C173
Dassault	Falcon 2000 To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase) (Battery Mod. avail. through Dassault)	FAA Design Approval	RG-380E/44LS	FAA-PMA Supplement No. 51, dd 02/21/03 and FAA TSO-C173
de Havilland Aircraft	See Bombardier Inc. & Viking Air Ltd			
Dornier	328-100	STC# ST00732DE	RG-380E/44LS (Battery)	FAA-PMA Supplement No. 98, dd 11/10/11
Embraer	EMB-110P1, EMB-110P2 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Embraer	EMB-110P1, EMB-110P2 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Embraer	EMB-500 (Phenom 100) (To replace lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	STC# SA01633WI	RG-390E	FAA-PMA Supplement No. 94, dd 09/09/11 and FAA TSO-C173
Embraer	135BJ, 135ER, 135LR, 135KE, 135KL, 145, 145EP, 145ER, 145LR, 145MP, 145MR, 145XR (To replace nickel-cadmium battery - Contact Concorde for replacement details prior to battery purchase)	STC# ST01520WI (Kit)	RG-442 (Battery) 5-0124 (TS-C4 Temperature Sensor)	FAA-PMA Supplement No. 86, dd 03/09/09 & P/N RG-442 is FAA TSO-C173 authorized.
Enstrom Helicopter	F-28F & 280FX	TC# H1CE, Rev. 20, Rev. A	RG24-11M (24V) & RG-35A (12V)	FAA-PMA Supplement No. 23, dd 04/04/96
Erco / Ercoupe	(See Univair)			
Eurocopter	AS350 B, BA, B1, B2, B3, D (To replace p/n 151CH-1 nickel-cadmium battery as a substitute for p/n 1606-1 as covered on the American Eurocopter STC)	FAA Design Approval	RG-350	FAA-PMA Supplement No. 52, dd 02/18/03 and FAA TSO-C173
Eurocopter	AS350 B, B1, B2, BA, C, D, D1 (To replace p/n 1606-1 nickel-cadmium battery)	STC# SR09185RC	RG-355	FAA-PMA Supplement No. 35, dd 03/06/98 and FAA TSO-C173
Eurocopter	AS355 E, F, F1, F2, N (To replace p/n 1606-1 nickel-cadmium battery)	STC# SR09186RC	RG-355	FAA-PMA Supplement No. 35, dd 03/06/98 and FAA TSO-C173
Eurocopter	BK-117-A-1, -A-3, -A-4, -B-1, -B-2, -C-1 (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	STC & STA# SR09034RC	RG-390E	FAA-PMA Supplement No. 21, dd 11/15/95 and FAA TSO-C173
Eurocopter	BO-105C & BO-105S (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	STC# SR09016RC	RG-390E	FAA-PMA Supplement No. 21, dd 11/15/95 and FAA TSO-C173
Eurocopter	EC130B4 (To replace p/n 151CH-1 nickel-cadmium battery – Contact Rotorcraft Support for details)	STC# SR02073LA	RG-350	FAA-PMA Supplement No. 88, dd 07/15/09 and FAA TSO-C173
Fairchild Aircraft	(See M-7 Aerospace)			
Garlick Helicopters	Bell UH-1F, UH-1P, TH-1F (To replace nickel-cadmium battery – Contact Tamarack for replacement details prior to battery purchase)	(Omitted temporarily pending STC number correction)	RG-390E	FAA-PMA Supplement No. 53, dd 03/26/03 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Global Amphibians	(See Revo Inc.)			
Globe	GC-1A, GC-1B	TC# A-766	RG-35A	FAA-PMA Supplement No. 63, dd 10/30/03
Grumman Aircraft	(See True Flight Holdings LLC)			
Gulfstream Aerospace	Galaxy/Gulfstream 200	STC# ST09945SC	5-0122	FAA-PMA Supplement No. 87, dd 04/13/09
Gulfstream Aerospace	Israel Aircraft Ind. Galaxy/Gulfstream 200 (To replace part no. 414377)	(Main battery obsolete – Contact Gulfstream for updated STC info.)	RG-380E/44C or RG-380E/60C	FAA-PMA Supplement No. 56, dd 05/27/03
Gulfstream Aerospace	Israel Aircraft Ind. Galaxy/Gulfstream 200 (To replace part no. 2778-18)	(Standby battery obsolete – Contact Gulfstream for updated STC info.)	RG-390E/C	FAA-PMA Supplement No. 56, dd 05/27/03
Gulfstream Aerospace	Israel Aircraft Ind. Galaxy/Gulfstream 200 (Temperature Sensor)	(New temp sensor assy. – Contact Gulfstream for updated STC info.)	5-0054 (CBC-Kit #TS-C2)	FAA-PMA Supplement No. 56, dd 05/27/03
Gulfstream Aerospace	(Gulfstream I) G-159 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Gulfstream Aerospace	GII (G-1159), GIII (G-1159A), GII (G-1159B) (DC System) (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST00773LA	RG-380E/44	FAA-PMA Supplement No. 40, dd 04/30/99 and FAA TSO-C173
Gulfstream Aerospace	GIII (G-1159A)(s/n 357, 402 & up), GIV (AC System) (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST00544LA (Kit)	RG-380E/44, 9713 Adaptor	FAA-PMA Supplement No. 38, dd 11/02/98 and FAA TSO-C173
Hawker Beechcraft	F33A, F33C, V35B, A36, A36TC	FAA Design Approval	CB24-11	FAA-PMA Supplement No. 5, dd 05/18/82
Hawker Beechcraft	77	FAA Design Approval	CB-25	FAA-PMA Supplement No. 1, dd 03/03/81 Amended: dd 03/03/88
Hawker Beechcraft	MU-300-10, 400, 400A (To replace nickel-cadmium battery – Contact Hawker Beechcraft for replacement details prior to battery purchase)	STC# SA2494SO	RG-380E/40B	FAA-PMA Supplement No. 22, dd 01/23/96 and FAA TSO-C173
Hawker Beechcraft	A200CT (Military) RC-12K	FAA Design Approval	TS-C6 (Temperature Sensor selling p/n 5-0125)	FAA-PMA Supplement No. 70, dd 05/28/04
Hawker Beechcraft	Kingair 65-90, 65-A90, B90, C90, E90, F90, 99, A100, B100, 200, 300, MU-300-10, 400, 400A, 400T, (T-1A) Concorde (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Hawker Beechcraft	Kingair 65-90, 65-A90, 65-A90-1 (JU-21A, U-21A, RU-21A, RG-21D, U-21G, RU-21H), 65-A90-4 (RU-21E, RU-21H), B90, C90, 65-A90-2 (RU-21B), 65-A90-3 (RU-21C), E90, H90 (T-44A), C90A, F90, 99, 99A, 99A (FACH), 100, A99, A99A, A100 (U-21F), B99, A100A, B100, C99, 200 (A100-1(U-21J)), A200C (UC-12B), 200C, B200, B200C (C-12F, UC-12F, UC-12M, C-12R), A200 (C-12A, C-12C), 200T, 200CT, A200CT (C-12D, C-12F, FWC-12D, RC-12D, RC-12F, RC-12G, RC-12H, RC-12K, RC-12P, RC-12Q), B200CT, B200T, 300, 300LW, B300, B300C, 1900, 1900C, 1900C (C-12J), 1900D (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# SA01260WI	RG-380E/40L RG-380E/40K RG-380E/44L RG-380E/44K RG-380E/60L RG-380E/60K	FAA-PMA Supplement No. 73, dd 08/11/04 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Hawker Beechcraft	Kingair 65-90, 65-A90, 65-A90-1 (Military U-21A, RU21A, RU21D, JU21A, U-21G, RU21H/GRV), 65-A90-4 (Military RU21E, RU21H/GRV & IV), B90, C90, 65-A90-2 (Military RU-21B), 65-A90-3 (Military RU-21C), E90, H90, (Military T-44A), C90A, F90, 99 & 99A, (Military 99A), 100, A99, A99A, A100 (Military U-21F), B99, A100A, B100, C99, 200, A200C, (Military UC-12), 200C, B200, B200C, (Military C12F, UC-12F & UC-12M), A200 (Military C-12A, C-12C), 200T, 200CT, A200CT (Military C-12D, FWC-12D, RC-12D, C-12F, RC-12G, RC-12H), B200CT, B200T, 200T, A100-1 (Military U-21J), A200CT (Military RC-12K), 1900, 1900C (Bladder Fuel), 1900C (Wet Wing), 1900C (Military C-12J), 1900D, 300, 300LW, B300, B300C, (S/N: FM-1 & subsequent, FN-1 & subsequent) (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	STC# SA00741WI	RG-380E/40K RG-380E/44K RG-380E/60K	FAA-PMA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02 and FAA TSO-C173
Hawker Beechcraft	65-90, 65-A90, B90, C90, E90, F90, 99, A100, B100, 200 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Hawker Beechcraft	200, 300, & B300 Series (To replace nickel-cadmium battery – Contact Hawker Beechcraft for replacement details prior to battery purchase)	STC# SA2699SO	RG-380E/40B	FAA-PMA Supplement No. 22, dd 01/23/96 and FAA TSO-C173
Hawker Beechcraft	400A (S/N RK-98 and after) (To replace Hawker Beechcraft part no. – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/40L	FAA-PMA Supplement No. 49, dd 1/23/03 and FAA TSO-C173
Hawker Beechcraft	Hawker 1000 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST00640LA (Kit)	RG-380E/60K	FAA-PMA Supplement No. 39, dd 04/23/99 and FAA TSO-C173
Hawker Beechcraft	BH.125 Series 1A, 1A/522, 1A/R-522, 1A/S-522; Series 3A, 3A/R, 3A/RA, BH.125 400A, 600A, HS.125 600A, 700A, BAe 125-800A; Hawker 800, 800XP (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST00415LA	RG-390E	FAA-PMA Supplement No. 39, dd 04/23/99 and FAA TSO-C173
Hawker Beechcraft	DH.125 Series, HS.125 Series, BH.125 Series (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase) (STC to replace emergency battery only)	STC# ST01223WI	RG-125	FAA-PMA Supplement No. 65, dd 01/30/04 and FAA TSO-C173
Hawker Beechcraft	400A Series (S/N's RK-98 and after) (To replace 38Ah lead-acid battery – Contact Hawker Beechcraft for replacement details prior to battery purchase)	STC# ST02506AT	RG-380E/44 RG-380E/44L RG-380E/60L	FAA-PMA Supplement No. 44, dd 06/13/02 and FAA TSO-C173
Hawker Beechcraft	35, A35, B35, C35, 35R, D35, E35, F35, G35, H35, J35, K35, M35, 35-33, N35, 35-A33, 35-B33, P35, S35, 35-C33, E-33, F-33, G-33, V35, V35A, V35B, 35-C33A, E33A, E33C, 36, A36, F33A, F33C, A36TC, B36TC, 23, A23, A23A, A23-19, A23-24, A24, 19A, M19A, B19, B23, C23, A24R, B24R, C24R	STC# SA00638WI	RG-35A RG-35AXC RG24-16	FAA-PMA Supplement No. 37, dd 06/22/98 Amended: dd 06/29/98 & FAA-PMA Supplement No. 82, dd 07/18/07 (to add RG24-16)
Israel Aircraft	(Jet Commander) 1121, 1121A, 1121B (Westwind) 1123, 1124 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Israel Aircraft	(Jet Commander) 1121, 1121A, 1121B (Westwind) 1123, 1124 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
JetProp LLC	Piper PA-46-310P, PA-46-350P (Included as part of STC for turbine conversion)	STC# ST00541SE	RG-46	FAA-PMA Supplement No. 54, dd 04/29/03
JetProp LLC	Piper PA-46-310P, PA-46-350P (Higher Capacity Replacement) (Included as part of STC for turbine conversion)	STC# ST00541SE	RG-49	FAA-PMA Supplement No. 54, dd 04/29/03 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Kaman Aerospace	K1200	TC# TR7BO	RG-380E/40B	FAA-PMA Supplement No. 26, dd 06/21/96 and FAA TSO-C173
Lake	(See Revo Inc.)			
Learjet	23, 24, 25, 28, 29, 35, 36 (To replace lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Learjet	23, 24, 25, 28, 29, 35, 36, 55 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Learjet	40, 45 (To replace Concorde part no. RG-443 – Contact the STC holder for replacement details prior to battery purchase) (STC for emergency battery only)	STC# ST01639WI (Kit)	RG-145-2	FAA-PMA Supplement No. 93, dd 09/09/11 and FAA TSO-C173
Learjet	45 (To replace lead-acid emergency battery – Contact Concorde for replacement details prior to battery purchase) (STC for emergency battery only)	STC# ST01173WI	RG-443	FAA-PMA Supplement No. 59, dd 06/23/03
Learjet	55	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 14, dd 02/07/91
M-7 Aerospace	Fairchild SA226-AT, SA227-AT, SA226-T, SA227-CC, -DC (RG-390ES replaces M-7 Aerospace p/n FASRG390ESTC)	FAA Design Approval	RG-390ES	FAA-PMA Supplement No. 60, dd 06/25/03 and FAA TSO-C173
M-7 Aerospace	Fairchild SA227AC, SA227BC (RG-390ES replaces M-7 Aerospace p/n FASRG390ESTC)	FAA Design Approval	RG-390ES	FAA-PMA Supplement No. 17, dd 06/27/95 and FAA TSO-C173
M-7 Aerospace	Fairchild SA226-T, SA226-T(B), SA227-TT (To replace p/n RG-91A which replaces M-7 Aerospace p/n FASRG91STC)	FAA Design Approval	RG-91	FAA-PMA Supplement No. 69, dd 05/17/04
Maule Aerospace Technology Inc.	M-4-210, M-4-220, M-4-180, M-5-180, M-5-210, M-5-220, M-5-235, M-5-210TC, M-5-200, M-6-180, M-6-235, M-7-235, M-7-235A, M-7-235B, M-7-235C, M-7-260, M-7-260C, M-8-235, MT-7-235, MT-7-260, MX-7-160, MX-7-160C, MX-7-180, MX-7-180A, MX-7-180B, MX-7-180C, MX-7-180AC, MX-7-235, MXT-7-160, MXT-7-180, MXT-7-180A	FAA Design Approval	RG-35A RG-35AXC	FAA-PMA Supplement No. 64, dd 01/06/04
MD Helicopter	MD369, 369A, 369D, 369F, 369FF, 369H, 369HM, 369HS, 369HE, 369E and 500N (To replace nickel-cadmium battery – Contact Adv. Pwr. For replacement details prior to battery purchase)	STC# SR00716SE (Kit)	RG-500 CBP-3349-2W (Connector – Selling p/n 4002) 9542 (Adaptor)	FAA-PMA Supplement No. 47, dd 12/02/02 & P/N RG-500 is FAA TSO-C173 authorized
MD Helicopter	600N (To replace nickel-cadmium battery with the connector receptacle on right side of battery container – Used for most 600N models)	STC# SR01564LA (Kit)	RG-600-1 CBP-3349-2W (Connector – Selling p/n 4002) 9542 (Adaptor)	FAA-PMA Supplement No. 67, dd 02/06/04 & P/N RG-600-1 is FAA TSO-C173 authorized
MD Helicopter	600N (To replace nickel-cadmium battery with the connector receptacle on left side of battery container)	STC# SR01564LA	RG-600-2 CBP-3349-2W (Connector – Selling p/n 4002) 9542 (Adaptor)	FAA-PMA Supplement No. 67, dd 02/06/04 & P/N RG-600-2 is FAA TSO-C173 authorized
MD Helicopter	MD-900 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# SR03895AT (Kit)	RG-407 Elbow Coupling Assy #5-0349 (Assy includes #8003, Elbow, vent adaptor, and Coupling #8086)	FAA PMA Supplement No. 92, dd 09/09/11 & P/N RG-407 is FAA TSO-C173 authorized.

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Mitsubishi	MU-2B, MU-2B-10, -15, -20, -25, -26, -26A, 30, 35, 36, 36A, 40, 60, MU-300-1, -1A (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Mitsubishi	YS-11A Series (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# SA2795SO	RG-390E	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Mooney	M20 (w/ R-33 or R-35 battery), M20A (w/ R-33 or R-35 battery), M20B, -20C, -20D, -20E, -20F, M20G, M20J (S/N 24-0001 to 24-2999), M20K (S/N 25-0001 to 25-0999)	Identity per 14 CFR § 21.303	RG-35A (To replace R-33) or RG-35AXC (To replace R-35)	FAA-PMA Supplement No. 77, dd 03/01/05
Mooney	M20J, M20K	STC# SA00081SE & STC# SA5691NM	RG-35A	FAA-PMA Supplement No. 24, dd 05/06/96
Mooney	M20J, M20K, M20L, M20M, M20R, M20S, M20TN (24V models)	Identity per 14 CFR § 21.303	RG24-11M (to replace manifold vented battery) or RG24-15	FAA-PMA Supplement No. 84, dd 02/01/08
Piaggio Aero Industries SpA	P180	STC# SA01653LA (Kit)	RG-380E/40L (Battery) 5-0242 (Temperature Sensor)	FAA-PMA Supplement No. 74, dd 09/27/04 & P/N RG-380E/40L is FAA TSO-C173 auth.
Pilatus Britten Norman Ltd.	(See B-N Group Ltd.)			
Pilatus	PC-12 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# ST00776LA	RG-380E/44	FAA-PMA Supplement No. 39, dd 04/30/99 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Piper	<p>PA-12, PA-12S, PA-18, PA-18 "105" (Special), PA-18 "125" (Army L-21B), PA-18 "135" (Army L-21B), PA-18 "150", PA-18A, PA-18A "135", PA-18A "150", PA-18S, PA-18S "105", PA-18S "125", PA-18S "135", PA-18S "150", PA-18AS "125", PA-18AS "135", PA-19 (Army L-18C), PA-19S, PA-20, PA-20 "115", PA-20 "135", PA-20S, PA-20S "115", PA-20S "135", PA-22, PA-22-108, PA-22-135, PA-22-150, PA-22-160, PA-22S-135, PA-22S-150, PA-22S-160, PA-23, PA-23-160, PA-23-235, PA-23-250 (Navy UO-1), PA-E23-250, PA-24, PA-24-250, PA-24-260, PA-25, PA-25-235, PA-25-260, PA-28-140, PA-28-150, PA-28-151, PA-28-160, PA-28-161, PA-28-180, PA-28-181, PA-28-201T, PA-28-235, PA-28-236, PA-28R-180, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-28S-160, PA-30, PA-31, PA-31-300, PA-31-350 & T-1020, PA-31-325 C/R, PA-32-260, PA-32-300, PA-32-301, PA-32-301T, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301, PA-32R-301T, PA-34-200, PA-34-200T, PA-34-220T, PA-36-285, PA-36-300, PA-36-375, PA-36-285, PA-38-112, PA-39, PA-40, PA-44-180, PA-44-180T TURBO, PA-46-310P, PA-46-350P, PA-60-600, PA-60-601, PA-60-601P, PA-60-602P, PA-60-700P, PA-400</p>	STC# SA01147WI (See Note 3)	<p>CB-25 CB-25XC RG-25 RG-25XC Replaces original battery p/n 450-030</p> <p>RG-25 Replaces original battery p/n 450-022</p> <p>CB-35A CB-35AXC RG-35A RG-35AXC Replaces original battery p/n 450-035 (Please note a replacement battery box cover may be required for the RG series— Contact CBC)</p> <p>CB24-11 RG24-11 RG24-15 Replaces original battery p/n 450-027 or 450-032</p> <p>CB24-11M RG24-11M RG24-15M Replaces original battery p/n 450-101</p> <p>RG24-20 Replaces original battery p/n 450-028, 450-031 or 450-029 (Please note an installation kit may be required – Contact CBC)</p>	FAA-PMA Supplement No. 50, dd 3/7/03
Piper	<p>PA-12, PA-12S PA-18, PA-19 (Army L-18C), PA-18 "125" (Army L-18A), PA-18 "135" (Army L-21B), PA-18A, PA-18A "135", PA-18 « 105 », PA-18S, PA-19S, PA-18S "125", PA-18S "135", PA-18AS "125", PA-18AS "135", PA-18S "105", PA-18 "150", PA-18A "150", PA-18S "150", PA-18A, PA-18A "135", PA-18A "150", PA-20, PA-20 "115", PA-20S, PA-20S "115", PA-20S "135", PA-20 "135", PA-22, PA-22-135, PA-22S-135, PA-22-150, PA-22S-150, PA-22-160, PA-22S-160, PA-22-108, PA-24, PA-24-250, PA-24-400, PA-24-260, PA-25, PA-25-235, PA-25-260, PA-23, PA-23, PA-23-160, PA-23-250 (Navy UO-1), PA-28-160, PA-28-150, PA-28-180, PA-28S-160, PA-28S-180, PA-28-235, PA-28-140, PA-28R-200, PA-28-151, PA-28-181, PA-28-161, PA-28R-201, PA-28R-201T, PA-28-236, PA-28RT-201, PA-28RT-201T, PA-28-201T, PA-32-260, PA-32-300, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301 (SP), PA-32R-301 (HP), PA-32R-301T, PA-32-301, PA-32-301T, PA-38-112, PA-36-285, PA-36-300, PA-36-375, PA-46-310P, PA-46-350P</p>	STC# SA00954WI (See Note 3)	<p>RG-25 or RG-25XC Replaces original battery p/n 450-030</p> <p>RG-35A or RG-35AXC Replaces original battery p/n 450-035</p> <p>RG24-11 or RG24-15 Replaces original Battery p/n 450-032</p> <p>RG24-11M or RG24-15M Replaces original battery p/n 450-101</p> <p>RG24-20 Replaces original battery p/n 450-031</p>	FAA-PMA Supplement No. 43, dd 09/04/01

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Piper	PA-23 Apache, PA-23-160, PA-23-250 (Navy UO-1), PA-23-235, PA-E-23-250 Aztec, PA-23-250, PA-31 Navajo, PA-31-300 Navajo, PA-31-350 Chieftan & T-1020, PA-31-325 Navajo C/R, PA-44-180 Seminole, PA-44-180T Turbo Seminole, PA-30 Twin Comanche, PA-39 Twin Comanche, PA-40 Twin Comanche, PA-34-200 Seneca, PA-34-200T Seneca II, PA-34-220T Seneca III, IV, V	STC# SA00954WI (See Note 3)	RG-25 or RG-25XC Replaces p/n 450-030 RG-35A or RG-35AXC Replaces p/n 450-035 RG24-11 or RG24-15 Replaces p/n 450-032 RG24-11M or RG24-15M Replaces p/n 450-101 RG24-20 Replaces p/n 450-031	FAA-PMA Supplement No. 61, dd 07/14/03
Piper	(Cheyenne) PA-31T, PA-31T1, PA-31T2, PA-31T3, PA-42, PA-42-720, PA-42-1000 (To replace nickel-cadmium battery – Contact Wilco for replacement details prior to battery purchase)	STC# SA00843WI	RG-380E/44L RG-380E/44K RG-380E/60L RG-380E/60K	FAA-PMA Supplement No. 80, dd 12/02/05 and FAA TSO-C173
Pitts	(See Aviat)			
Raytheon	(See Hawker Beechcraft)			
Revo Inc.	(Lake) LA-4, LA-4-200, Model 250 (S/N: 1-25 only)	FAA Design Approval	RG-35A or RG-35AXC	FAA-PMA Supplement No. 25, dd 06/07/96
Robinson Helicopter	R-22	TC# H10WE	RG-25XC	FAA-PMA Supplement No. 75, dd 02/18/05
Robinson Helicopter	R-44	TC# H11MN	RG-25XC (12V), RG24-15 (24V)	FAA-PMA Supplement No. 75, dd 02/18/05
Sabreliner	NA 265, NA 265-20, -30, -40, -70, -80 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Sabreliner	NA 265, NA 265-20, -30, -40, -70, -80 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Sabreliner	265-40, -60, -65, -70, -80 (To replace nickel-cadmium battery – Contact Jet Harbor for replacement details prior to battery purchase)	STC# ST01294AT	RG-380E/44	FAA-PMA Supplement No. 36, dd 04/20/98 and FAA TSO-C173
Sabreliner	265-65 (To replace nickel-cadmium battery – Contact Jet Harbor for replacement details prior to battery purchase)	STC# ST01294AT	RG-206	FAA-PMA Supplement No. 36, dd 04/20/98 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-30 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44	FAA-PMA Supplement No. 29, dd 01/17/97 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-30 (To replace emergency nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-126	FAA-PMA Supplement No. 29, dd 01/17/97 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-60 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-380E/44	FAA-PMA Supplement No. 28, dd 01/17/97 Amended: dd 02/21/97 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-60 (To replace emergency nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	FAA Design Approval	RG-126	FAA-PMA Supplement No. 28, dd 01/17/97 Amended: dd 02/21/97 and FAA TSO-C173
Sikorsky	CH-54B	STC# SR01241SE	RG-390E	FAA-PMA Supplement No. 78, dd 3/2/05 and FAA TSO-C173
Sikorsky	S-76A (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# SR00091LA	RG-380E/40B	FAA-PMA Supplement No. 19, dd 08/24/95 and FAA TSO-C173
Sikorsky	S-76B (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase) (Two each RG-390E Req.)	STC# SR03819AT	RG-390E	FAA-PMA Supplement No. 91, dd 04/09/10 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate No. (or FAA Design Approval)	CBC Part Number	Battery / Part FAA Approval Type
Sikorsky	S-76A, C, C+ (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase)	STC & STA# SR09050RC	RG-380E/44	FAA-PMA Supplement No. 22, dd 01/23/96 and FAA TSO-C173
Slingsby Aviation	Firefly Models T67M260 & T67M260-T3A	TC# A73EU Rev. 2 BA 17, Issue 6	RG24-11M	FAA-PMA Supplement No. 27, dd 07/03/96
Socata	TBM 700 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase)	STC# SA00775LA	RG-380E/44	FAA-PMA Supplement No. 39, dd 04/23/99 and FAA TSO-C173
Stinson	(See Univair)			
Tamarack Helicopters	Bell UH-1F, TH-1F, UH-1P (To replace nickel-cadmium battery – Contact Tamarack for replacement details prior to battery purchase)	STC# SR01349LA	RG-390E	FAA-PMA Supplement No. 53, dd 03/26/03 and FAA TSO-C173
Tiger Aircraft	(See True Flight Holdings LLC)			
True Flight Holdings LLC	AA-1, AA-1A, AA-1B, AA-1C, AA-5, AA-5A, AA-5B, AG-5B	STC# SA01250WI	CB-25 CB-25XC RG-25 RG-25XC RG24-11M RG24-15M	FAA-PMA Supplement No. 71, dd 06/04/04
Twin Commander	680T, 680V, 680W, 690, 690A, 690B, 690C, 695, 695A, 690D & 695B	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Twin Commander	680T, 680V, 680W, 690, 690A, 690B, 690C, 695, 695A, 690D & 695B	FAA Design Approval	RG-380E/44	FAA-PMA Supplement No. 15, dd 01/06/91 and FAA TSO-C173
Univair (Erco)	415-C, 415-D, 415-CD (S/N 113 and up)	TC# A-718 Rev. 29, dd 07/14/05	CB-25 or RG-25	FAA-PMA Supplement No. 79, dd 11/23/05
Univair (Erco)	Ercoupe: 415-E, 415-G, 415F-1 (All S/N's) Forney: F-1A (S/N 5715 – 5729)	TC# A-787 Rev. 33, dd 07/14/05	CB-25 or RG-25	FAA-PMA Supplement No. 79, dd 11/23/05
Univair (Erco)	Forney: F-1A (S/N 5730 and up) Alon: A-2, A-2A (All S/N) Mooney M-10 (All S/N)	TC# A-787 Rev. 33, dd 07/14/05	RG-25	FAA-PMA Supplement No. 79, dd 11/23/05
Univair (Stinson)	Stinson: 108, 108-1, 108-2, 108-3, 108-5	TC# A-767 Rev. 27, dd 07/14/05	CB-35A or RG-35A	FAA-PMA Supplement No. 79, dd 11/23/05
Viking Air Ltd	DHC-6-1, -100, -200, -300 (To replace nickel-cadmium battery or lead-acid – Contact Concorde for replacement details prior to battery purchase)	STC#SA0397AT	RG-380E/60L or RG-380E/44 (Main) RG-300 (Aux.- Optional) 5-0455 (Mating Connector) (Aux – Optional) 4000 (Connector) (AN-3150 lead-acid replacement only)	FAA-PMA Supplement No. 79, dd 11/23/05