



Part Design Approval

This approval is issued to:

Marsh Brothers Aviation Inc.
3225 Mainway
Burlington, Ontario
Canada L7M 1A6

Number: PDA24-9

Issue No.: 1

Approval Date: May 31, 2024

Issue Date: May 31, 2024

Responsible Office:

Prairie and Northern

Aeronautical Product Type or Model:

Beechcraft Corporation 35, 35-33, 35-A33, 35-B33, 35-C33, 35-C33A, 35R, 36, 56TC, 58, 58A, 58P, 58PA, 58TC, 58TCA, 95, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B, 95-C55, 95-C55A, A35, A36, A36TC, A56TC, B35, B36TC, B95, B95A, C35, D35, D55, D55A, D95A, E33, E33A, E33C, E35, E55, E55A, E95, F33, F33A, F33C, F35, G33, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B.
Hawker Beechcraft G36, G58.

Canadian Type Certificate or Equivalent:

3A15 (Beechcraft Corporation 35-33, 35-A33, 35-B33, 35-C33, 35-C33A, 36, A36, A36TC, B36TC, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B)
3A16 (Beechcraft Corporation 56TC, 58, 58A, 95, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B, 95-C55, 95-C55A, A56TC, B95, B95A, D55, D55A, D95A, E55, E55A, E95)
A-245 (Hawker Beechcraft G36)
A-259 (Hawker Beechcraft G58)
A-777 (Beechcraft Corporation 35, 35R, A35, B35, C35, D35, E35, F35, G35)
A23CE (Beechcraft Corporation 58P, 58PA, 58TC, 58TCA)

Replacement Part:

Seat Roller and Slide Button Replacement

- See Continuation Sheet -

Conditions: The installation of the approved part is to be limited only to the type / model of aeronautical product(s) listed above.

DocuSigned by:

3499A33FD63D42E...

Loy Y. Liew
For Minister of Transport



NOTE: THIS ADDENDUM SHALL REMAIN PART OF THE CERTIFICATE REFERRED TO THEREIN.

Installation/Operating Data, Required Equipment and Limitations:

Manufacturing of the replacement Seat Roller and Slide Button must be in accordance with Transport Canada Civil Aviation (TCCA) approved Marsh Brothers Aviation (MBA) Master Data List ML-M23002; Revision NC dated 25 Mar 2024 or later TCCA approved revision.

Replacement parts are to be installed, inspected, and maintained in accordance with the applicable maintenance manuals appropriate to the aircraft listed above. Replacement parts introduce no new limitations or maintenance requirements.

ELIGIBILITY LIST

Original OEM P/N	MBA P/N	Part Description
118641	MBA-03-10005-1	Seat Roller
102-530087-35	MBA-03-10006-1	Slide Button

– End –