

Flap Actuators:

Flap Actuators (Overhauled):

Part Number	Core Charge	Notes
101-521016-1	1,000.00	
101-521016-2	1,000.00	
129-521050-1	1,000.00	
129-521050-2	1,000.00	
129-521051-1	1,000.00	
129-521051-2	1,000.00	
45-521212-604	1,000.00	With Drive Gear
45-521212-607	1,000.00	With Drive Gear
45-521212-6604	1,000.00	
45-521212-6607	1,000.00	
45-521212-6608	1,000.00	
45-521212-6609	1,000.00	
50-521152-1	1,000.00	With Drive Gear
50-521152-2	1,000.00	With Drive Gear
50-521153-1	1,000.00	With Drive Gear
50-521153-2	1,000.00	With Drive Gear
50-521198-3	1,000.00	With Drive Gear
50-521198-4	1,000.00	With Drive Gear
50-521222-3	1,000.00	
50-521222-4	1,000.00	
50-521223-3	1,000.00	
50-521223-4	1,000.00	
90-521024-1	1,000.00	
90-521024-2	1,000.00	

All overhauls include new piston & plug assembly

Flap Motors:

Beechcraft Flap Motor and Gearbox (Overhauled):

Part Number	Core Charge	Notes
100-384040	556.00	ElectroMech Motor for 100-524073-1
100-384040 FS36	556.00	Aerospace Controls
100-384040-3	556.00	ElectroMech Motor for 100-524073-1
100-524073-1	1,000.00	Motor & Gearbox with pipethreads
100-524074-1	600.00	Gearbox only
35-364151-53	600.00	
35-364151-55	600.00	12V: 35-380109
35-364151-57	600.00	24V
99-524025-3	350.00	
99-524025-7	600.00	